



GUJARAT INDUSTRIES POWER COMPANY LIMITED
(Surat Lignite Power Plant)

Date: 17.04.2024

NOTE:

Sub: Surat Lignite Power Plant: 4X125 MW: Structural stability certificate of GIPCL School (Bhartiya Vidya Bhavan's) building.

We have constructed 1st phase of school building (G+1) with infrastructure facility in year 2006 & 2nd phase (G+1) in year 2011. Total construction area of 1st phase is: 24975 sq.ft & 2nd phase is 27294 sq.ft.


As per education department (government of Gujarat) Surat office, required structural stability certificate.

Previous stability certificate issued by sister concern of M/s. D. H. Patel & Associates, Surat of agency/person Mr. Bharat D. Bhavsar of M/s. Shreeji Associates, Surat vide W.O. No.: SLPP/Civil/Colony/School/stability/2019/1890 dated 14.06.2019. The same is going to expire on 16.06.2024.

On approval note dated 15.03.2024, we have issued work order to M/s. D. H. Patel & Associates Pvt. Ltd Surat, vide ref no.: SLPP/Civil/Colony/School/stability/2024/840 dated 02.04.2024 for obtaining fresh Certificate of Stability for School building


The representative of M/s. D.H.Patel & Associates Pvt. Ltd Surat has site visited on 09.04.2024 and visual checking done.

Sister concern of M/s. D.H.Patel & Associates Pvt. Ltd Surat of agency/person Mr. Bharat D. Bhavsar of Shreeji Associates Surat has issued 03 sets of Stability certificate of GIPCL School (Bhartiya Vidya Bhavan's) building vide Ref no: BVB/01 dated 09.04.2024 for validity of 5 Years (i.e. up to 08.04.2029). Please find attached herewith 02 sets of stability certificate issued by Bharat D. Bhavsar for your record please.



(Anil Patel)
Sr. Manager (Civil)

Through: AGM (Civil) 

To: AGM (HR&A)


Principal
Bhartiya Vidya Bhavan's
GIPCL Academy
Nani Naroli, Ta : Mangrol,
Dist.: Surat-394 112




Secretary
BVB's GIPCL Academy



SHREEJI ASSOCIATES

CHARTERED ENGINEER & COMPETENT PERSON

CERTIFICATE OF STABILITY

Certificate No :- BVB/01

Date: 09/04/2024

1. Name of the School : **BHARATIYA VIDYA BHAVAN'S
(GIPCL ACADEMY)**
2. Village town & district which the School is situated : Nani Naroli , Taluka :- Mangrol,
Dist :- Surat , Gujarat-394110
3. Full postal address of the School : Nani Naroli , Taluka :- Mangrol,
Dist :- Surat , Gujarat-394110
4. Name of the Occupier of the School : **GUJARAT INDUSTRIES POWER COMPANY
LTD**
5. Nature of process to be Occur. : School (Education Foundation)
6. Number of floors . : Ground +1 Floor.

Remark : Instructions for protection of structure must be followed as per annexure attached with this certificate.

I **Bharat D. Bhavsar** certify that I have inspected the above said premises & the drawing provided by **BHARATIYA VIDYA BHAVAN'S (GIPCL ACADEMY)** and examined various structure Members. I am of the opinion that all the works of **BHARATIYA VIDYA BHAVAN'S (GIPCL ACADEMY)** construction in the premises is structurally sound & that its stability will not be endangered by its use as a School (Education Foundation.)

Signature: BDBhavsar

Bharat D. Bhavsar

Chartered Engineer (M-1761285)

B.E. (Civil), A.M.I.E., L.L.B.



Principal

Bharatiya Vidya Bhavan's
GIPCL Academy

Nani Naroli, Ta : Mangrol,
Dist : Surat 394 112



Secretary

NEXT TEST DUE ON :- 08/04/2029

204, BABUBHAI CHAMBERS, ATHWA GATE, SURAT - 1 (GUJ.) Mob. No. :- +91 9426158923, +91 8200909005
E-mail : shreejiassociates2017@yahoo.in



SHREEJI ASSOCIATES

CHARTERED ENGINEER & COMPETENT PERSON

ANNEXURE

Ref. Stability Certificate No :- BVB/01

Dated: 09/04/2024

INSTRUCTIONS ATTACHED TO THE CERTIFICATE OF STABILITY

- 1) This certificate stands valid if preventive maintenance of structure is carried out regularly.
- 2) The structure shall be maintained in good working condition, shall be regularly inspected & any small crack, bending, tilting, leaning or any change appearance in the structure fabrication shall be immediately informed to the respective authority for right assessment, decision & suggestion for maintenance of safe structure.
- 3) This certificate does not take any liability for an accident that may occurred due to fire, earthquake, Process Problems, Overloading any abnormal calamities and any kind of unauthorized construction by client
- 4) Water deposited at plinth level nearby to RCC or steel column and on terrace floor level shall be avoided.
- 5) All rules & regulations for fire safety implemented by Government must be followed strictly.

Signature: BDBhavsar
Bharat D. Bhavsar
Chartered Engineer (M-1761285)
B.E. (Civil), A.M.I.E., L.L.B.



[Signature]
Principal
Bharatiya Vidya Bhavan's
GIPCL Academy
Mangrol, Ta: Mangrol,
Dist: Surat 394 112



[Signature]
Secretary
BVB's GIPCL Academy

